

TROUBLE SHOOTING GUIDE FOR POWDER COATING

TROUBLE	POSSIBLE CAUSE	POSSIBLE SOLUTIONS
1) Problems related to Elect	rostatic Coating Operation	:
Poor charging - inadequate	High voltage source not	Check high voltage source is on &
Powder build or wrap on part	providing enough kv at charging	check continuity from voltage
	electrode or grid	source to electrode
OR		Replace missing or broken
		electrode insulated by powder build
Pull-way or tearing - Coating		Clean electrode insulated by
film shrinks leaving bear substrate		powder build
	Poor ground	Check ground from conveyor
		rail through hanger to part. All
		areas must be free from grease
		& insulating material
	Powder delivery is too high	Turn down powder feed
	Excessive moisture in powder	Moisture in humid air will
	booth air	tend to dissipate humidity in
		the powder spray area
	Powder too fine	Too much reclaim added to
		virgin powder
		Virgin powder pulverised too
		fine by manufacturer
	Powder type or formula	Some resin type charged better
		than others & some formulas are
		designed for specific application
	Powder delivery air too high -	Turn down air setting or move
	Powder blowing by part	gun position away from parts
2. Poor Penetration - Faraday cage	Powder delivery too low	Increase powder delivery air settings
		Use barrel extension
	Poor ground	Check ground from conveyor
		rail through hanger to part. All
		areas must be free from grease
		& insulating material
	Powder spray pattern too wide	Select smaller deflector
	 Voltage too high 	Turn voltage setting down so powder
		builds on parts edges & leading surfaces
		do not repel powder from corners



		T
	Powder delivery velocity too high	Turn air setting down so
		powder/air stream does not blow
		powder from corners
	 Poor gun placements 	Adjust gun position so powder
		cloud has direct path to recess area
	 Powder too fine 	Too much reclaim added to virgin powder
		Virgin powder pulverised too
		fine by manufacturer
3. Back charging - Powder layers	Voltage to high .	Turn down Voltage setting
are repelled from part in spots.	Gun positioned to close to part	Change gun placement away from part
	• poor ground	Check ground from conveyor
		rail through hanger to part. All
		areas must be free from grease
		& insulating material
	Powder too fine .	Too much reclaim added to
		virgin powder
		Virgin powder pulverized too
		fine by manufacturer
4. Powder picks up charge	Powder booth air to dry	Adjust humidity of powder spray area
through powder hoses.	Poor delivery and/or reclaim	Provide ground for all equipment
	equipments ground	
5. Powder feed spurting or	• insufficient air pressure volume	check air supply. Air supply to
slugging - Interrupted		piping and equipment is sufficient or not.
powder feed		Enough air volume must be provided.
	Hoses kinked,flattened or too long	Check powder feed hoses
	Hoses, pump venturies or guns	Clean hoses, venturies and guns
	clogged with powder.	Check air supply for moisture that
		causes powder compaction.
		Check spray booth air humidity
		Check powder supply for
		contamination. Check reclaim sieve.
6. Poor spray pattern -not a	Worn gun parts.	Replace worn feed tubes, orfices
symmetrical powder cloud		deflectors and covers.
	Impact fusion build	Clean gun parts as needed
	Delivery (feed) air too low.	Check air supply. Increase air
		for powder feed
	Hoses, venturies or gun blocked	Clean hoses, venturies and guns
	with powder	,
	5000.	



Contamination in reclaim powder	Reclaim in - line sieve torn,	Replace sieve or repair as
	missing or in operable	necessary.
	Powder or dirt falling in spray	Clean conveyor regularly (or
	booth from conveyor or hangers	continuously) before entering powder
		spray booth. Strip hangers as needed.
	Contamination from parts	Check cleaning and pre treatment
	entering spray booth .	equipment and ensure proper part
		drainage before spray booth.
	Contamination form plant air	Isolate spray booth area.
	circulated through spray booth	Preferably enclose in a room filtered &
		humidity controlled air.
2. Spray booth dusting -	Bag or cartride filters blinding	Clean/replace bags or cartridge filters
Inadequate air flow through		Check spray booth air humidity
spray booth		Check reverse air cleaning
	Final filters clogged .	Check filter bag/cartridge for powder
		leakage, repair or replace as needed
	Too large of open area in spray	Reduce open area. Increased opening
	booth housing	reduces booth air velocity
	Powder delivery (feed) to high	Reduce the number of spraying or the
		amount of powder to each gun.

1. Poor impact resistance /	Under cured	Increase oven temperature
poor flexibility		Increase dwell time in oven
	poor cleaning or pre-treatment	Check pre-treatment equipment & chemicals
	Film thickness too high	Reduce film thickness by adjusting
		application equipment .
	Change in substrate thickness	Check substrate with supplier
	or type	
	 Powder resin type or formula 	Check with powder manufacturer
2. Poor adhesion	Poor cleaning or pre-treatment	Check pre-treatment process and chemicals
	Change in substrate.	Check substrate with supplier
	Under cured	Increase oven temperature
		Increase dwell time in oven
	 Powder resin type or formula 	Check with powder manufacturer
3. Poor corrosion resistance	Poor cleaning or pre-treatment	Check pre-treatment equipment and
		chemicals



	Under cured	Increase oven temperature
		Increase dwell time in oven
Poor chemical resistance	Under cured	Increase oven temperature
		Increase dwell time in oven
	Powder resin type or formula	Check with powder manufacturer
5. Poor pencil hardness or poor	Under cured	Increase dwell time in oven
abrasion resistance	Powder resin type or formula	Check with powder manufacturer
6. Too much orange peel	Film thickness too thin	Increase film thickness by ajusting
Poor surface flow		application equipment
	Heat-up rate too slow	Increase oven temperature
		Modify oven bafflling to increase
		heat rate
	Powder resin type or formula	Check with powder manufacturer
7. Gloss too low for high gloss powder	Incompatible powder	Clean application equipment before
	contamination	changing powders
	Micro-pinholing from gassing	Check substrate for porosity
		Check substrate for moisture
		Check powder for moisture from
		reclaim or compressed air
		 Check film thickness, coating to thick
	Over cured film	Check oven temp.
	Powder resin type or formula	Check with powder manufacturer
8. Gloss to high for a low gloss	Under cured.	Increase temperature of oven
powder		• Increase dwell time in oven
	Powder formula	Check with powder manufacturer
9. Contamination in powder	Virgin powder contaminated	Check with powder manufacturer
10. Inconsistent film thickness.	Guns positioned wrong	Check & reposition guns so that spray
		patterns overlap slightly
	Reciprocators not matched to	Adjust line speed. Adjust reciprocator
	line speed.	stroke
	Air flow in booth disturbing	Consult your equipment supplier
	spray pattern	
	Defective spray equipment	Correct the Spray Pattern properly
11. Off color.	Improper oven exhaust	Check exhaust vent fans
	Bake time too long	Adjust line speed
	Oven temperature too high	Lower oven temperature
	Variation in film thickness	Check the Problem of "Inconsistent
		film thickness".
	Powder formula	Check with powder manufacturer
	I.	ı



12. Pinholing and gassing	Micro-pinholing from gassing	Check substrate for porosity
through coating surface		Check substrate for moisture
		Check powder for moisture from
		reclaim or compressed air.
		Check film thickness, coating to thick
13. Pull-way or tearing - Coating	Poor cleaning metal preparation	Check pre-treatment process dry of
film shrinks leaving bear	or dry off	oven and part drainage
substrate		

4) Problems related to Powde	er Applications :	
Poor fluidizing properties in	Pressure of fluidizing air too low	Adjust (increase) pressure of fluidzing air
the powder hopper	Fluidizing membrane is blocked	Clean/replace the fluidzing membrane
	Humidity of compressed air too	Install an air dryer with corresponding
	high	oil - micro filter or another suitable drying
		system
	Humidity of the powder to high	Check storage facilities. Powder shall be
		stocked at room temperature (30°c) in
		closed packing (max.humidity 60%)
	• Free flowing properties of the	Contact your powder supplier
	powder poor.	
2. Blockage in venturies and hoses	• Fusing of the powder in the venturi	Clean or replace the hoses, if necessary
		reduce pressure of powder of transport air
	• Fusing of the powder in the hoses	Clean the hose by bending & breaking up
		the fused powder if necessary replace it
	• Fusing of the powder in the hoses	Install an air dryer with a corresponding
		oil micro filter or an air dryer with a
		corresponding oil micro filter or another
	Bad free flowing properties of the	Contact your powder supplier
	powder	
B. Blockage in the gun .	• Fusing in the gun or gun outlet	Clean the gun according to instruction
		of your equipment supplier.When blocking
		occurs frequently - check humidity of
		compressed air and the free flowing
		properties of the powder.
	Blockage caused by	Clean the gun according to instruction
	contamination of the powder	of equipment supplier & determine the
	with dust or other coarse	reason of this contamination (chk powder
	materials	pumps for possible impact fusion .Impact



	fusion particles which break of in the pump
	could be transported to the spray gun &
	result in blockage)

Insufficient wrap around	Poor electrostatic charging of the	Adjust level of electrostatic kilovoltage
	powder	(increase) if not possible, check equipment
		and guns according to instructions of the
		equipment supplier
		Check for broken electrodes on the spray
		gun. If found, replace electrodes
		Check for possible frictional transport
		through powder hose. If found, consult
		powder supplier for hose material
		recommendation.
	Insufficient ground contact	Check the ground contacts using a
		measuring device. Correct and insure
		sufficient earth to ground control
	Output of powder too low	Trun up powder delivery air setting
	Using an unsuitable powder	Contact your powder supplier
	type	
2. Poor penetration into corners	Output of powder too low	Trun up powder delivery air setting
flanges, slots, etc.	Insufficient ground contact	Check the ground contacts and if necessary
		use a suitable measuring instrument
	Powder cloud too wide	Narrow powder cloud. If necessary install a
		more suitable deflector or adjust air for
		cone adjustment
3. Poor adherence of powder to	Poor electrostatic charging of	Adjust level of electrostatic kilo-voltage
part, powder falls from part easily	the powder	
	 Powder output too high or the 	Reduce powder output and or
	pressure for the transport air to	reduce pressure of the transport air
	high, which blow the powder	
	from the object	
	Unsuitable particle size	Contact your powder supplier
	distribution of the powder or	
	unsuitable powder type for	
	object	



1. Dust, precured or other	 Dust or other coarse parts on the 	 Check pretreatment high sludge
coarse material	metal surface	level in phosphate bath
	Dust or other coarse parts in	Check powder & locate the cause
	powder	of this contamination. If possible
		use fresh or sieved powder
2. Matting of powder surface	Contamination with other	Clean up powder coating
	powder of different formulations	equipments or contact your powder
		supplier
3. Orange peel	Warming up of the coated	Check curing cycle or curing oven.
	material is too slow or too fast	Contact your powder supplier
		for exact curing procedure
	Powder type too fine or too	Contact your powder supplier
	coarse particle size distribution	
	Moisture contamination	Replace powder
4. Cratering	Contamination with other	Clean up powder coating
	powder	equipments or contact your powder
		supplier
	Bad pretretment	Check pretreatment & if necessary
		contact your pretreatment supplier
	Contamination with	Check the presence of incompatible
	incompatible material from the	material if required clean up powder
	spraying area (i.e.silicones)	coating equipments or contact your
		powder supplier
5. Pinholing	Humidity of powder too high	Check storage facility. Powder
		to be stored at room temp. in
		close packing. Max.humidity 75%
	Air entrapement in casting	Preheat object over 160° C
		and cool down before application
	Gas entrapement and escaping	Keep coating thickness below
	due to chemical reaction	100 microns if necessary contact
		your powder supplier